

Termination Board

The Termination board is required for testing the P6470, P6471, P6472, P6473, and P6474 probes. Refer to Figure 4-1 for connector locations.




Figure 4-1: Termination Board